APPENDIX B

Clean Copy of Changes to Paragraphs Made in Amendment Filed August 1, 2002

Page 8, between lines 33 and 34:

As shown in Fig. 9, internal ribs 44 are located along central portions 43 of the sidewalls.

Page 9, between lines 25 and 26:

As shown in Fig. 18, container 76 has two pairs of substantially parallel flat sidewalls 80a, 80b, 82a, 82b joined together at corner areas. As shown, a height of the first pair 80a, 80b is approximately equal to a height of the second pair 82a, 82b.

Page 9, between lines 21 and 23:

As seen in the embodiments of Figs. 8, 10, 12, 14 and 16, and their respective cross sections, the sidewalls' outer surfaces are smooth at least in those regions opposite the vertically oriented ribs formed on the sidewall's inner surfaces.

- 14 - DC1 - 328059.1